Fujifilm Cares About The Environment

Fujifilm and its subsidiaries have tirelessly and steadily continued its efforts and activities in the realm of environmental preservation. Fujifilm is dedicated to "preserving a green Earth and its environment, preserving health, and preserving safety." As part of this effort, FUJIFILM Medical Systems U.S.A., Inc. is providing the following information on Fujifilm Computed Radiography (FCR) Imaging Plate disposal.



Fujifilm Imaging Plate Disposal



Many products used on a regular basis at healthcare facilities such as oil, fluorescent light bulbs, sharps, disposable surgical supplies, and test specimens must be disposed of in a specialized manner. Your FCR Imaging Plates (IPs) contain a small amount of barium which must be discarded in accordance with the laws of your state and the U.S. Environmental Protection Agency (EPA). The disposal of used IPs must be handled by a licensed transport and disposal company and must not be disposed of by anyone else.

Fujifilm Will Help

Fujifilm has provided this simplified brochure to guide you in the proper disposal of your IPs, which should make compliance easier! Questions? Please call your local Fujifilm CR Specialist or call (800) 431–1850.

Attached you will find:

- 1. Sample EPA ID# Application.
- 2. Sample Manifest.
- 3. List of State Environmental Agencies.

Your Responsibilities

Your facility may already have an EPA identification number. If you do not, you may need to apply for an EPA ID number from your state by filling out a form similar to the one attached. Your state environmental protection agency has this form, if you need one (see the attached list of state offices). The used IPs must be removed by an authorized transporter and disposal organization. Please remember that you are ultimately responsible for how the used IPs are disposed.

Step By Step Instructions:

- 1. Apply for an EPA identification #, if necessary.
- 2. Have the used IPs removed by an authorized organization (your state environmental protection agency can help you locate an authorized and reputable disposal organization).
- 3. Prior to removal of the used IPs, ensure that the transporter has a manifest which is accurate and similar to the one attached to this brochure.
- 4. Ensure that a copy of the manifest is forwarded to you within 35 days of the day the used IPs were accepted by the transporter.
- 5. Assure that you or your transporter provides copies of the manifest to both the origin and recipient states.
- 6. The paperwork must be maintained by your organization for a minimum of three years.

Imaging Plate Disposal





FUJIFILM Medical Systems U.S.A., Inc. 419 West Avenue Stamford, CT 06902 (800) 431-1850

1. Sample EPA ID# Application.

RCRA SUBTITLE C SITE IDENTIFICATION FORM, EPA Form 8700-12, can be downloaded from the following as well as the instructions. The form is at the end of the document:

http://www2.epa.gov/sites/production/files/2015-02/documents/8700-12 2015.pdf

2. Sample Manifest.

Uniform Hazardous Waste Manifest, EPA form 8700-22, can be downloaded from the following: http://www3.epa.gov/epawaste/hazard/transportation/manifest/pdf/newform.pdf

WHERE CAN I OBTAIN ASSISTANCE?

To obtain assistance in filling out the **Notification of Regulated Waste Activity, RCRA Hazardous Waste Part A Permit Application, or the Hazardous Waste Report**, you may call or e-mail your State or EPA Regional Office contact for detailed assistance. Some States have reporting requirements in addition to those shown in the Federal booklet. See the list below for State and EPA Regional Office addresses, contact names, telephone numbers, and e-mail addresses.

STATE OFFICE CONTACT INFORMATION

Please return your forms to the appropriate State or EPA Regional Office listed below. Call or email the contact identified below for additional information.

Note: Some States use the Federal Form, while others use a State Form. See the list for this information.

STATE ADDRESS

Alabama (RCRA Hazardous Waste Part A Permit

(Federal or State Form) Application and Hazardous Waste Report-(Federal Form) Notification of Regulated Waste Activity-

(State Form))

Alabama Department

of Environmental Management Permits and Services Division

P.O. Box 301463

Montgomery, AL 36130-1463

Alaska U.S. EPA Region 10

(Federal Form) Office of Air Waste and Toxics

1200 Sixth Avenue, Suite 900, M/S AWT-122

Seattle, WA 98101-3140

Arizona Arizona Department of Environmental Quality

(Federal Form) Waste Programs Division

UST & Division Support Section

GIS & IT Unit Mail Code 4415A-1

1110 West Washington Street

Phoenix, AZ 85007

Arkansas Arkansas Department of Environmental Quality

(State Form) Hazardous Waste Division

5301 Northshore Drive,

North Little Rock, AR 72118-5317

California USPS:

(ID Number California Department of Toxic Substances Control

State Form) Generator Information Services Section

P.O. Box 806

Sacramento, CA 95812-0806

USPS:

California Department of Toxic Substances Control

(800) 618-6942

(916) 255-1136 (if calling from outside U.S.)

Biennial Report (BR)

Office of Data Evaluation & Environmental

Indicators P.O. Box 806

Sacramento, CA 95812-0806

UPS/FedEx:

California Department of Toxic Substances Control

Biennial Report

Office of Data Evaluation & Environmental

Indicators

10011 I Street, Floor 11 Sacramento, CA 95814

Colorado Colorado Department of Public Health

(Federal or and Environment

State Form) HMWMD (Mailcode HMWMD-HWP-B2)

4300 Cherry Creek Drive South

Denver, CO 80246-1530

Connecticut Connecticut Department of Energy and

(Federal Form) Environmental Protection

Bureau of Materials Management and

Compliance Assurance

Waste Engineering and Enforcement Division

79 Elm Street

Hartford, CT 06106-5127

Delaware Delaware Department of Natural Resources

(Federal Form) and Environmental Control

Solid and Hazardous Waste Management Section

89 Kings Highway Dover, DE 19901

District ofColumbia
Government of the District of Columbia
District Department of the Environment

(Federal form) Hazardous Materials Branch

1200 First Street, NE, 5th Floor

Washington, D.C. 20002

Florida Florida Department

(Federal Form) of Environmental Protection

Hazardous Waste Management Section

MS-4550

2600 Blair Stone Road Tallahassee, FL 32399-2400

Georgia Department of Natural Resources

(Federal Form) Land Protection Branch

Hazardous Waste Management Programs

Suite 1154 1066, East Tower 2 Martin Luther King, Jr. Dr. SW-

Atlanta, GA 30334-9000

Guam RCRA Notification Hazardous Waste Report

(State Form) Guam Environmental Protection Agency

P.O. Box 22439 Barrigada, GU 96921

Building 17-3304 Mariner Avenue

Tiyan, Guam 96913

Hawaii Hawaii Department of Health

(Federal Form) Solid and Hazardous Waste Branch

Room 212

919 Ala Moana Boulevard

Honolulu, HI 96814

Idaho Department of Environmental Quality

(Federal Form) Waste Management & Remediation Division

2nd Floor

1410 North Hilton Boise, ID 83706

Illinois Environmental Protection Agency

(Federal & Records Management Division MC16 State Form) P.O. Box 19276

Springfield, IL 62794-9276

Illinois Environmental Protection Agency

Bureau of Land, MC 33

P.O. Box 19276

Springfield, IL 62794-9276

Illinois Environmental Protection Agency

Bureau of Land, MC 24

P.O. Box 19276 Springfield, IL 62794-9276

http://www.dep.state.fl.us/waste/categories/hazadous/pages/BRS data htm

Part A State Form:

www.gaepd.org/Documents/epdforms hwb.htm

l#management

Indiana Data Services Section

(State Form) Regulatory Reporting Section

Office of Land Quality

Indiana Department of Environmental Management

100 North Senate Avenue, Room 1101

Indianapolis, IN 46204-2251

Iowa U.S. EPA Region 7 (Federal Form) AWMD/WEMM

11201 Renner Boulevard Lenexa, Kansas 66219

Kansas Regulations and Data

(State Form) KDHE, Bureau of Waste Management

1000 SW Jackson, Suite 320 Topeka, Kansas 66612-1366

www.kdheks.gov/waste

Kentucky Kentucky Division of Waste Management

(State Form) Hazardous Waste Branch

200 Fair Oaks Ln Frankfort, KY 40601

Louisiana Department of Environmental Quality

(Federal Form) OES, Permit Support Services Division

P.O. Box 4313

Baton Rouge, LA 70821-4313

[located at 602 N. Fifth Street, B.R., LA 70802]

Maine Department of Environmental Protection

(Federal Form) Bureau of Remediation & Waste Management

Division of Oil and Hazardous Waste Facilities

Regulation Ray Building

State House Station 17 Augusta, ME 04333-0017 [Located at 28 Tyson Drive]

Maryland Department of the Environment

(Federal Form) Hazardous Waste Program

Suite 650

1800 Washington Boulevard Baltimore, MD 21230-1719

(Federal Form) Protection

Minnesota

Bureau of Waste Prevention

7th Floor

One Winter Street Boston, MA 02108

Michigan Department of Environmental Protection

(Federal Form) Waste and Hazardous Materials Division

P.O. Box 30241

Minnesota Pollution Control Agency

(Federal Form) Regulatory Data Management

Operational Support Division

520 Lafayette Road

St. Paul MN 55155

Mississippi Mississippi Department of Environmental Quality (Federal Form) Environmental Compliance & Enforcement Division

P.O. Box 2261

Jackson, MS 392225-2261

[located at 515 East Amite Street Jackson, MS

39201]

Missouri Department of Natural Resources

(Federal Form) P.O. Box 176

Jefferson City, MO 65102

http://www.mass.gov/dep

135-3312---,00.html

http://www.pca.state.mn.us/

http://www.michigan.gov/deg/1,16077-

Montana Montana Department of Environmental Quality (Federal Form Waste & Underground Tank Management Bureau

for Notification Hazardous Waste Section

& State Form P.O. Box 200901 for Reporting) Metcalf Building

1520 East Sixth Avenue Helena, MT 59620

http://deq.mt.gov/HazWaste/default.mcpx

Navajo Nation Navajo Nation Environmental Protection Agency (Federal Form) Waste Regulatory Compliance Department

Old DNR Bldg - Window Rock Blvd. Bldg. #2695

P.O. Box 339

Window Rock, AZ 86515

Nebraska Biennial Report forms should be mailed to:

(Federal Form) Nebraska Department of Environmental Quality

Waste Management Section,

Compliance Unit

1200 N Street, The Atrium Building, Suite 400

Lincoln, NE 68509-8922

Nevada Nevada Department of Conservation and

(Federal Form) Natural Resources

Division of Environmental Protection

Suite 4001

901 S. Stewart Street

Carson City, NV 89701-5249

New New Hampshire Department
Hampshire of Environmental Services

(Special P.O. Box 95

Procedure Concord, NH 03302

contact state) [located at 29 Hazen Drive]

New Jersey Notification of Regulated Waste Activity/Site

(Federal Form) <u>Identification forms/Biennial Report Forms and</u>

Part A forms

NJ Department of Environmental Protection Hazardous Waste Compliance & Enforcement

9 Ewing St. 3rd Flr.

Mail Code 09-03 P.O. Box 420

Trenton, NJ 08625-0420

New Mexico Environment Department

(Federal Form) Hazardous Waste Bureau

2905 Rodeo Park Dr. East Building 1

Santa Fe, NM 87505-6303

Waste Management Section

Compliance Unit (402) 471-4210 (main) (402) 471-2186 (alt.)

Phone: (609) 292-2913 (main)

(609) 943-3019 (alt.)

www.nmenv.state nm.us/hwb/index htm

New York Biennial Report forms should be mailed to:

(Federal Form) New York State Department of

Environmental Conservation

Division of Environmental Remediation

625 Broadway, 12th Floor Albany, NY 12233-7250

Notification of Regulated Waste Activity/Site Identification forms (not included as part of a Biennial Report) EPA Form 8700-12 and Part A

Form 8700-23 should be mailed to:

USEPA Region 2

CASD – Hazardous Waste Programs Branch

Att: RCRA Notifications 290 Broadway, 22nd Floor New York, NY 10007-1866

North North Carolina Department of Environment and

Carolina Natural Resources

(Federal Form) Division of Waste Management

Hazardous Waste Section (DWM-HWS)

P.O. Box MSC1646 Raleigh, NC 27699 217 W. Jones Street Raleigh, NC 27603

North Dakota North Dakota Department of Health

(Federal Form) 2301 8th Avenue, N

Fargo, ND 58102

Ohio Environmental Protection Agency

(State Form) Division of Materials and Waste Management

P.O. Box 1049

Columbus, OH 43216-1049

RCRA Notification Section

(212) 637-4106

www.ndhealth.gov/wm

Notification (State Form)

Part A (Federal Form & State Info.)

 $\underline{http://epa.ohio.gov/dmwm/Home/Notiform.as}$

px

Biennial Report Form (State Form)

http://www.epa.ohio.gov/dmwm/Home/HWAnnualReportProgram.aspx

Oklahoma Department of Environmental Quality

(Federal Form) Land Protection Division

Data Management Section 707 North Robinson Avenue

PO Box 1677

Oklahoma City, OK 73102

Oregon Oregon Department of Environmental Quality

(Federal Form) 811 S. W. Sixth Avenue

Portland, OR 97204-1390

http:www.deqhazwaste.net

Pennsylvania Hazardous Waste Biennial Report Forms (only)

(Federal Form) PA Department of Environmental Protection

Bureau of Waste Management

Division of Reporting and Fee Collection

P.O. Box 8550

Harrisburg, PA 17105-8550

for UPS or FedEx: 400 Market Street, 14th Floor

Harrisburg, PA 17101-2301]

Notification of Hazardous Waste Activity Forms

(only)

PA Department of Environmental Protection

Bureau of Waste Management

Division of Hazardous Waste Management

Notification Section P.O. Box 69170

Harrisburg, PA 17106-9170

[for UPS or FedEx: 400 Market Street, 14th Floor

Harrisburg, PA 17101]

Hazardous Waste Part A Permit Application

Forms(only)

PA Department of Environmental Protection

Bureau of Waste Management

Division of Hazardous Waste Management

P.O. Box 69170

Harrisburg, PA 17106-9170

[for UPS or FedEx: 400 Market Street, 14th Floor

Harrisburg, PA 17101]

Puerto Rico Biennial Report forms should be mailed to:

(Federal Form) Puerto Rico Environmental Quality Board

P.O. Box 11488 Santurce, PR 00910

Notification of Regulated Waste Activity/Site

Identification forms (not included as part of a Biennial Report) EPA Form 8700-12 and Part A

Form 8700-23 should be mailed to

USEPA Region 2

CASD - Hazardous Waste Programs Branch

Attn: RCRA Notifications 290 Broadway, 22nd Floor New York, NY 10007-1866 **RCRA Notifications Section**

(212) 637-4106

Rhode Island Rhode Island Department of Environmental

(Federal Form) Management

Office of Waste Management 235 Promenade Street Providence, RI 02908-5767

South South Carolina Department of Health

Carolina and Environmental Control

(State Form) Bureau of Land and Waste Management

2600 Bull Street

Columbia, SC 29201-1708

South Dakota South Dakota Department of Environment

(Federal Form) and Natural Resources

Waste Management Program 523 East Capitol Avenue

Pierre, SD 57501

http://www.scdhec.gov/environment/a

dmin/htm/eqc forms.asp

Biennial Report & Notification

Form:

Biennial Report Form:

http://denr.sd.gov/des/wm/hw/hwbien

nial.aspx

Part A Permit Form:

http://denr.sd.gov/des/wm/hw/hwmai

npage.aspx

Tennessee Tennessee Department of Environment and

(State Form) Conservation

Division of Solid Waste Management

5th Floor

401 Church Street

Nashville, TN 37243-1535

Texas Texas Commission on Environmental Quality

Registration and Reporting Section MC 129

P.O. Box 13087

Austin, TX 78711-30087

Trust RCRA Notification and Hazardous Waste Report

Territories U.S. EPA Region 9

75 Hawthorne Street WST-6 San Francisco, CA 94105

Utah Utah Department of Environmental Quality

Solid and Hazardous Waste

P.O. Box 144880

Salt Lake City, UT 84114-4880 Express Delivery Address:

195 North 1950

West, Salt Lake City, UT 84116

Vermont Vermont Department of Environmental Conservation

West Building (Federal Form)

> 103 South Main Street Waterbury, VT 05671-0404

Virgin Islands U.S. EPA Region 2

(Federal Form) Division of Environmental Planning and Protection

> CASD – Hazardous Attn: RCRA Notifications 290 Broadway, 22nd floor New York, NY 10007-1866

Virginia Virginia Department of Environmental Quality (Federal Form) Division of Land Protection and Revitalization

> 629 E. Main Street Richmond, VA 23219

Washington State Department of Ecology Washington Hazardous Waste and Toxic Reduction (State Form)

P.O. Box 47658

Olympia, WA 98504-7658

West Virginia West Virginia Department of Environmental

(Federal Form) Protection

601 57th Street

Charleston, WV 25304

Wisconsin Wisconsin Department of Natural Resources

Bureau of Waste and Materials Management (State Form)

P.O. Box 7921

Madison, WI 53707-7921

[located at 101 South Webster Street]

Wyoming Wyoming Department of Environmental Quality

(Federal Form) Solid & Hazardous Waste Division

> 122 West 25th Street Cheyenne, WY 82002

RCRA Notification Section

Receptionist will direct you to

(608) 266-2111

appropriate WIDNR Regional Office

(212) 637-4106

- 10 -